



# JEPPESEN<sup>®</sup>

## Chart Alert

**!! URGENT !!**

**Date:** 14 January 2022

**Subject:** Rio De Janeiro, Brazil  
Santos Dumont (SBRJ)  
RNP L Rwy 02R (22-6)

***Crossing Altitude Incorrect***

The RNP L Rwy 02R chart dated 24 DEC 21 (effective 30 December 2021) depicts an incorrect crossing altitude at the fix RJ051 on the missed approach.

The correct crossing altitude at RJ051 is **Maximum 3000 feet**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE  
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The revised RNP L Rwy 02R (22-6) will be issued in the 4 FEB 22 revision. This Chart Alert is also posted on the Jeppesen Web site.

[Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

**+1 (303) 328-6776 (Western Hemisphere)**

**+49 (6102) 50-8174 (Eastern Hemisphere)**

**U.S. Toll Free: 1-800-353-2107**

**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).