



JEPPESEN®

NavData® Alert

!! URGENT !!

Date: 25 November 2022

Subject: Male, Maldives
Velana Intl (VRMM)
Multiple procedures
Cycles 2211 & 2212

Procedure coding incorrect

Jeppesen NavData for cycle 2211, effective 03 November 2022 and cycle 2212, effective 01 December 2022, contains incorrect data for Velana Intl; Male, Maldives (VRMM). AMDT 001-22 - dated 17 NOV 22 was received after the ICAO specified date for aeronautical information publication.

- **STAR AQAXA 1B [AQAX1B]:** Altitude at waypoints **MM522** and **MM425** should read “**at or above**” **5500'**
- **STAR TENIV 1B [TENI1B]:** Altitude at waypoints **MM522** and **MM425** should read “**at or above**” **5500'**
- **STAR HOKEY 1B [HOKE1B]:** Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “**at or above**” **5500'**
- **STAR ATSON 1B [ATSO1B]:** Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “**at or above**” **5500'**
- **STAR PATLO 1B [PATL1B]:** Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “**at or above**” **5500'**
- **STAR ELBET 1B [ELBE1B]:** Altitude at waypoint **MM424** should read “**at or above**” **5500'**
- **STAR ESKOL 1B [ESKO1B]:** Altitude at waypoint **MM424** should read “**at or above**” **5500'**
- **STAR MISAQ 1B [MISA1B]:** Altitude at waypoint **MM424** should read “**at or above**” **5500'**
- **STAR DALSO 1B [DALSO1B]:** Altitude at waypoint **MM424** should read “**at or above**” **5500'**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

- **STAR AQAXA 1A [AQAX1A]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR TENIV 1A [TENI1A]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR HOKEY 1A [HOKE1A]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR ATSON 1A [ATSO1A]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR PATLO 1A [PATL1A]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR MUNUT 1C [MUNU1C]:** Altitude at waypoints **MM503** and **MM502** should read “**at or above**” **5500'**
- **STAR ELBET 1A [ELBE1A]:** Altitude at waypoint **MM505** should read “**at or above**” **5500'**
- **STAR ESKOL 1A [ESKO1A]:** Altitude at waypoints **RONJI** and **MM505** should read “**at or above**” **5500'**
- **STAR MISAQ 1A [MISA1A]:** Altitude at waypoints **RONJI** and **MM505** should read “**at or above**” **5500'**
- **STAR DALSO 1A [DALSI1A]:** Altitude at waypoint **MM501** should read “**at or above**” **5500'**
- **STAR MUNUT 1A [MUNU1A]:** Altitude at waypoint **MM505** should read “**at or above**” **5500'**
- **STAR NASIM 1A [NASI1A]:** Altitude at waypoint **MM505** should read “**at or above**” **5500'**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2213, effective 29 December 2022. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
 +1-303-328-4445 (Western Hemisphere)
 +49 610 250 8175 (Eastern Hemisphere)
 E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.