



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 30 Nov 2022

Subject: Cranfield, UK
Cranfield (EGTC)

RNP Rwy 03 and RNP Rwy 21 – Incorrect missed approach procedures

The standard charts 12-1 and 12-2 (dated 16 SEP 22) for Cranfield (EGTC), UK contain incorrect information for the missed approach procedure for the RNP Rwy 03 and RNP Rwy 21 procedures.

The correct missed approach procedures should read:

RNP Rwy 03:

“Climb to 2500’ on track 031° to NDB CIT to join the holding.”

RNP Rwy 21:

“Climb straight ahead to 1500’, then climbing LEFT turn to 2500’ to join the NDB CIT holding.”

Charts 12-1 and 12-2 will be corrected in revision 9 DEC 22.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen’s Web site at www.jeppesen.com.