



# **JEPPESEN®**

## **Chart Alert**

**!! URGENT !!**

**Date:** 30 November 2022

**Subject:** Kuala Lumpur, Malaysia  
Kuala Lumpur Intl – Sepang (WMKK)  
VOR DME Rwy 14L (23-1)  
VOR DME Rwy 15 (23-2)  
VOR DME Rwy 32R (23-3)  
VOR DME Rwy 33 (23-4)

*New procedures.*

Amendment 004-22 AIRAC, effective 01 DEC 22 added four new VOR DME procedures. The following new Jeppesen charts were previously deferred but will be available in the **9 DEC 22 revision: VOR DME Rwy 14L (23-1), VOR DME Rwy 15 (23-2), VOR DME Rwy 32R (23-3), VOR DME Rwy 33 (23-4).**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE  
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The charts for VOR DME Rwy 14L (23-1), VOR DME Rwy 15 (23-2), VOR DME Rwy 32R (23-3), VOR DME Rwy 33 (23-4) will be available in the 9 Dec 22 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:  
**+1 (303) 328-6776 (Western Hemisphere)**  
**+49 (6102) 50-8174 (Eastern Hemisphere)**  
**U.S. Toll Free: 1-800-353-2107**  
**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).