



# JEPPESEN®

## Chart Alert

### **!! URGENT !!**

**Date:** 1 December 2022

**Subject:** Lusaka, Zambia  
Kenneth Kaunda Intl

***Incorrect Information about Apron, Taxiways and Aircraft Stands***

The Zambia AIRAC AIP SUP 004/2022 (dated 11 Nov 22 / effective 1 Dec 22) was received too late and it was impossible to publish the new information in time.

The Jeppesen Airway Manual charts 10-9 and 10-9A for Lusaka (FLKK), Zambia, Kenneth Kaunda airport were updated with revision 25 Nov 22 for the 1 Dec 22 effective date. But, both charts do **not** contain the information from AIRAC AIP SUP 004/2022.

The AIRAC AIP SUP 004/2022 is incorporated with revision 9 DEC 22.

The updated charts (dated 9 DEC 22) are attached to this alert and are available for download from [www.jeppesen.com](http://www.jeppesen.com).

**The updated charts (dated 9 DEC 22) have to be used immediately after receipt as they are effective 1 DEC 22.**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE  
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

If you have any questions concerning this Chart Alert, please contact Chart Support at:

**+1 (303) 328-6776 (Western Hemisphere)**

**+49 (6102) 50-8174 (Eastern Hemisphere)**

**U.S. Toll Free: 1-800-353-2107**

**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).