



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 9 February 2023

Subject: Lima-Callao, Peru
Jorge Chavez Intl (SPJC)
GAVOX 2F [GAVO2F] & GAVOX 2G [GAVO2G] DEPARTURES (ALL RWYS) (10-3B)

Initial climb text incorrect.

Jeppesen chart dated 20 Jan 23 (effective 26 January 2023) contains incorrect initial climb text for GAVOX 2F procedure for Rwy 16L/R. The correct Initial Climb text should be as follows:

Rwy 16L: Climb on runway heading to 750 or above, turn RIGHT on JCL R205 (heading 205°), intercept LPA R272 (heading 272°) to D15.0 LPA **at or below 6000**, climb on course LPA R272 (heading 272°) to D27.0 LPA, turn RIGHT on course SLS R178 (heading 258°) to GAVOX.

Rwy 16R: Climb on runway heading to 600 or above, turn RIGHT on JCL R205 (heading 205°), intercept LPA R272 (heading 272°) to D15.0 LPA **at or below 6000**, climb on course LPA R272 (heading 272°) to D27.0 LPA, turn RIGHT on course SLS R178 (heading 258°) to GAVOX.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected chart for GAVOX 2F [GAVO2F] & GAVOX 2G [GAVO2G] DEPARTURES (ALL RWYS) (10-3B) will be reissued in the next available revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.