

!! URGENT!!

Date: 16 May 2024

Subject: El Oued, Algeria

Guemar (DAUO) Multiple procedures

Procedure information incorrect

Jeppesen charts dated 24 JUN 22 contain incorrect information for Guemar; El Oued, Algeria (DAUO).

[11-1] ILS Z or LOC Z Rwy 13 should read LOC Z Rwy 13. FAF altitude should read 2080'.

[11-2] ILS Y or LOC Y Rwy 13 should read LOC Y Rwy 13. FAF altitude should read 2080'.

[13-1] VOR Rwy 13 - FAF altitude should read 1810'.

[10-9] Runway 13/31 length should read 2550m.

Declared distances TORA/TODA/LDA RWY 13/31 should read 2550m. ASDA RWY 13/31 should read 2650m/2550m.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The revised charts will be reissued in the 31 MAY 24 revision. This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107 E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.