



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 13 May 2024

Subject: Muscat, Oman
Muscat Intl (OOMS)

ILS or LOC Rwy 08L (11-1)
RNP Rwy 08L (12-1)
RNP Rwy 08R (12-3)
RNP Rwy 26L (12-4)

Procedure information not included/outdated

Jeppesen chart library does not include charts for two new RNP procedures to runway 08R/26L at Muscat Intl; Muscat, Oman (OOMS). Oman AIP AIRAC SUP 005/2024 (effective 16 MAY 24) contains newly added instrument approach procedures for Rwy 08R and Rwy 26L and waypoint changes. The new procedure charts and waypoint changes could not be published in time and are therefore not included in revision 10 MAY 24, effective 16 MAY 24.

Below charts and procedures are missing from library:

- **RNP Rwy 08R (12-3)**
- **RNP Rwy 26L (12-4)**

On the Jeppesen charts listed below, waypoint **M20WL** should read **BOTID**.

- **ILS or LOC Rwy 08L (11-1)**
- **RNP Rwy 08L (12-1)**

The procedure charts will be published in revision 17 MAY 24 and are added to this Chart Alert.

The published charts (dated 17 MAY 24) will be effective 16 May 2024.

The charts are also available for download from www.jeppesen.com

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.