



# **JEPPESEN<sup>®</sup>**

## **Chart Alert**

**!! URGENT !!**

**Date:** 18 July 2024

**Subject:** AI Udeid, Qatar  
AI Udeid AB (OTBH)  
ILS or LOC Rwy 34L (11-3)

*Incorrect ILS DME frequency*

Jeppesen chart, ILS or LOC Rwy 34L (11-3) dated 7 JUN 24, (Eff 13 Jun), has the incorrect frequency for ITCE ILS DME. The correct frequency for ITCE ILS DME should be **111.10**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE  
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected ILS or LOC Rwy 34L (11-3) chart will be reissued in the 2 AUG 24 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

**+1 (303) 328-6776 (Western Hemisphere)**

**+49 (6102) 50-8174 (Eastern Hemisphere)**

**U.S. Toll Free: 1-800-353-2107**

**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).