



!! URGENT !!

Date: 05 August 2024

Subject: Luxembourg, Luxembourg
Luxembourg (ELLX)
Multiple procedures
Cycle 2408

Procedure coding incorrect

Jeppesen NavData for cycle 2408, effective 08 August 2024, contains incorrect data for Luxembourg; Luxembourg, Luxembourg (ELLX).

ILS or LOC Z Rwy 06 and RNP Rwy 06 – transition **BETEX 1D [BET1D]** is missing from database.

ILS or LOC Z Rwy 24 and RNP Rwy 24 – transition **BETEX 1C [BET1C]** is missing from database, transition **OXCAM 3C [OXC3C]** should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2409, effective 05 September 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Luxembourg, Luxembourg (ELLX) 10-2F and 10-2G charts dated 2 AUG 24 (effective 08 August 2024) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

ELLX_2408