



JEPPESEN[®]

Chart Alert

!! URGENT !!

Date: 1 August 2024

Subject: Deming, NM
Deming Muni (KDMN)
VOR-B (13-1)

Procedure turn on wrong side of outbound course.

The Jeppesen chart VOR-B (13-1) dated 17 FEB 23 (effective 23 Feb) has the procedure turn depicted on the wrong side of the outbound course. The procedure turn should be depicted on the **RIGHT side of the outbound course, 070 degrees outbound, RIGHT turn to 115 degrees, LEFT turn to 295 degrees and LEFT turn to 250 degrees inbound.**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected VOR-B (13-1) chart will be reissued in the 30 Aug 24 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.