

!! URGENT !!

Date: 23 December 2024

Subject: Lorient, France Lann-Bihoue (LFRH) Multiple procedures

Procedure information outdated

Jeppesen charts contain incorrect information for Lorient; Lann-Bihoue, France (LFRH). FRANCE MIL AMDT 001-25 (MIAC 2) (eff 26 DEC 24) was received after the ICAO specified date for aeronautical information publication.

STAR RNAV Rwy 25 procedures (10-2 dated 29 NOV 24) **ERCOZ 2M [ERCO2M], LENSU 2M [LENS2M]** and **BAGAD 2M [BAGA2M]** should not be used.

STAR RNAV Rwy 20 procedures (10-2A dated 29 NOV 24) ERCOZ 2N [ERCO2N], LENSU 2N [LENS2N], QPR 2N [QPR2N] and BAGAD 2N [BAGA2N] should not be used.

STAR Rwy 07 procedures (10-2B dated 29 NOV 24) LENSU 1L [LENS1L] and QPR 1L [QPR1L] should not be used.

SID Rwy 20 procedures (10-3B, 10-3D and 10-3F dated 14 JUN 24) **BAGAD 1C [BAGA1C], BAGAD 1S** [BAGA1S], LENSU 1S [LENS1S] and ROSPO 1S [ROSP1S] should not be used.

Radar PAR Rwy 07 (18-3, dated 24 MAY 24) procedure withdrawn.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected procedure charts will be reissued in revision 10 JAN 25 (for SIDs) and 24 JAN 25 (for Approach). This Chart Alert is also posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have any questions concerning this Chart Alert, please contact Chart Support at: Support Portal: support.jeppesen.com E-mail: chartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.