



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 21 January 2025

Subject: Tiruchirappalli, India
Tiruchirappalli (VOTR)

VOR Rwy 09 (13-1)

VOR Rwy 27 (13-2)

Procedure information not current

Jeppesen chart library does not contain current information for Tiruchirappalli; Tiruchirappalli, India (VOTR). India AIRAC SUP 284-24 and SUP 285-24, both effective 23 January 2025, could not be incorporated in time and contain revised instrument approach procedure information for Rwy 09 and 27.

The procedure charts listed below could not be published in time and are therefore not included in revision 17 JAN 25, effective 23 January 2025:

- **VOR Rwy 09 (13-1, dated 13 DEC 24, effective 26 December 2024) - Procedure completely revised, do not use.**
- **VOR Rwy 27 (13-2, dated 13 DEC 24, effective 26 December 2024) - Procedure completely revised, do not use.**

The revised procedure charts will be published in revision 31 JAN 25 and will be attached to this chart alert once available. The published charts (dated 31 JAN 25) are effective 23 JAN 2025.

The charts will also be available for download from www.jeppesen.com

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: support.jeppesen.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.