



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 13 October 2021

Subject: Ho Chi Minh, Vietnam
Tan Son Nhat Intl (VVTN)
Cycle 2110

Existing parking stands renamed and new parking stands added

Jeppesen Airport Moving Map and A816 formatted data for cycle 2110, effective 07 October 2021, contains incorrect data for Tan Son Nhat Intl; Ho Chi Minh, Vietnam (VVTN). Vietnam AIP SUP A27/21, published 06 October 2021, effective 14 October 2021, announced renaming of 14 existing parking stands and introduction of 12 new parking stands. It was received after the ICAO specified date for aeronautical information publication, therefore following changes (effective 17:01 [UTC] on 14 October 2021) are not reflected in cycle 2110 data:

Renamed parking stands:

- 1T to 20T
- 2T to 15T
- 4T to 2T
- 5T to 1T
- 6T to 16T
- 7T to 14T
- 8T to 6T
- 9T to 7T
- 10T to 19T
- 11T to 18T
- 12T to 17T
- 13T to 12T
- 14T to 13T

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:
U.S. Toll Free: 1-800-537-7725
Direct: 1-303-328-4170
E-mail: GISDataSupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

Added parking stands:

- 4T (located on TWY Z2, between stands 23 and 26)
- 5T (located on TWY Z2, between stands 24 and 25)
- 8T (located on TWY Z1, between stands 35 and 36)
- 9T (located on TWY Z3, between stands 41 and 42)
- 10T (located on TWY Z3, between stands 43 and 46)
- 11T (located on TWY S5, between TWY Z3 and Z4)
- 12A (located East of stand 12)
- 12B (located West of stand 12)
- 14A (located East of stand 14)
- 14B (located West of stand 14)
- 16A (located East of stand 16)
- 16B (located West of stand 16)

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2111, effective 04 November 2021. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: GISDataSupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.