



JEPPESEN[®]

Chart Alert

!! URGENT !!

Date: 25 November 2022

Subject: Nordholz, Germany
Nordholz (ETMN)
[10-3] SID MN 108 [MN108]
[10-3] SID MN 126 [MN126]

Procedure information incorrect

Jeppesen chart dated 10 SEP 21 contains incorrect information for Nordholz, Germany (ETMN). Germany CENOR FLIP VOL 2, effective 01 December 2022 was received after the ICAO specified date for aeronautical information publication.

- [10-3] SID MN 108 [MN108] – Routing should read: **Climb on track 075° to 2000', continue as cleared by ATC.**
- [10-3] SID MN 126 [MN126] – Routing should read: **Climb on track 255° to 2000', continue as cleared by ATC.**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected charts will be reissued in the 9 DEC 22 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

For the coded NavData approach procedures, refer to the NavData Alert posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.