

!! URGENT!!

Date: 27 September 2023 Subject: Colombia, Ecuador

Enroute Airway

Incorrect Enroute Airway MEA

Jeppesen Enroute chart SA (LO) 3 dated 23 JUN 2023 depicts incorrect Enroute Airway MEAs for portions of G675 within Colombia and Ecuador.

The correct MEAs are shown below.

G675 Mercaderes (MER) VOR - SEKTA Intersection MEA 12,000'.

G675 SEKTA Intersection - GAVEK Intersection MEA 16,000'.

G675 GAVEK Intersection - Ipiales (IPI) VOR MEA 16,000'.

G675 Ipiales (IPI) VOR - DUBKU Intersection MEA 18,000.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Changes will be made to SA (LO) 3 and the chart will be published in a future revision. Until then an entry will appear in the Chart Change Notices, and this Alert will be posted on the Jeppesen Web site (http://www.jeppesen.com/company/alerts/aviation-alerts).

If you have any questions concerning this Chart Alert, please contact Charting Technical Support at:

U.S. Toll Free: 1-800-353-2107 Direct: 1-303-799-9090, Extension 5830

E-mail: ChartSupport@jeppesen.com

Chart Alerts (formerly ChartWatch Notices) are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. These Alerts are distributed to affected chart users and are also available on Jeppesen's Web site at www.jeppesen.com.