

## **!! URGENT !!**

Date: 8 May 2024

Subject: Kalaburagi, India Kalaburagi (VOGB) ILS or LOC Rwy 27 (11-1) VOR Rwy 27 (13-1)

## New procedures unavailable.

India AIRAC AIP Supplement 75/2024 dated 04 April 2024, effective 16 May 2024 includes a new procedure, ILS or LOC Rwy 27 (11-1), at Kalaburagi airport in India. This procedure is unavailable and will not be published in the 10 May 24 revision. India AIRAC AIP Supplement 74/2024 dated 04 April 2024, effective 16 May 2024 includes a new procedure, VOR Rwy 27 (13-1), at Kalaburagi airport in India. This procedure is unavailable and will not be published in the published in the 10 May 24 revision.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The new ILS or LOC Rwy 27 (11-1) and VOR Rwy 27 (13-1) procedures will be published in the 17 May 24 revision. This Chart Alert is also posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have any questions concerning this Chart Alert, please contact Chart Support at: +1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere) U.S. Toll Free: 1-800-353-2107 E-mail: ChartSupport@basing.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at <u>www.jeppesen.com</u>.