

!! URGENT!!

Date: 5 July 2024

Subject: Al Hoceima, Morocco

Cherif El Idrissi Intl (GMTA)

ILS Rwy 17 (11-1)

Procedure information not included

Jeppesen charts contain incomplete information for Cherif El Idrissi Intl; Al Hoceima (Morocco, GMTA). Morocco AIP SUP AIRAC 004/2024 (eff 11 JUL 24) contains a newly added ILS procedure for Rwy 17. The new procedure chart could not be published in time and is therefore not included in revision 5 JUL 24, for the 11 JUL 24 effective date.

The procedure chart will be published in revision 12 JUL 24 and is added to this Chart Alert. The published chart (dated 12 JUL 24) will be effective 11 July 2024. The chart is also available for download from www.jeppesen.com

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere) U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.