



# JEPPESEN®

## Chart Alert

**!! URGENT !!**

**Date:** 19 July 2024

**Subject:** Harlingen, Texas  
Valley Intl (KHRL)  
RNAV (GPS) Y Rwy 18R (12-3)

*FAF label in briefing strip incorrect*

Jeppesen RNAV (GPS) Y Rwy 18R (12-3) chart dated 5 JUL 24 (effective 11 July 2024) has FAF label in the briefing strip depicted incorrectly. The correct FAF label should read **CIXEN**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE  
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected chart for RNAV (GPS) Y Rwy 18R will be reissued in the next available revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

**+1 (303) 328-6776 (Western Hemisphere)**

**+49 (6102) 50-8174 (Eastern Hemisphere)**

**U.S. Toll Free: 1-800-353-2107**

**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).