

!! URGENT!!

Date: 11 July 2024

Subject: Malacky, Slovakia

Malacky (LZMC)
Multiple procedures

Procedures outdated

Jeppesen charts contains incorrect information for Malacky; Malacky Slovakia (LZMC). Slovakia MIL AIP AMDT 047-24 dated 11 JUL 24 changes could not be published in time.

- ILS or LOC Rwy 19 should read ILS or LOC Z Rwy 19.
- ILS or LOC Y Rwy 19 is missing from database.
- Departures RWY 19:

SID BERVA 4A [BERV4A] should read **BERVA 1P [BERV1P]**, SID ODNEM 3A [ODNE3A] should read **ODNEM 1P [ODNE1P]**, SID BERVA 1N is missing from database,

SID ODNEM 1N is missing from database.

 Arrivals RWY 19: STAR BERVA 3A [BERV3A] should read BERVA 1S [BERV1S], ODNEM 2A [ODNE2A] should read ODNEM 1S [ODNE1S].

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected charts will be reissued in the 19 JUL 24 revision (Approach) and 26 JUL 24 revision (SID/STAR) and added to this Chart Alert when available. This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere) U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.