



JEPPESEN[®]

Electronic Chart Alert

!! URGENT !!

Date: 30 September 2024

Subject: Canada
Enroute Waypoint
Cycle 2410

Waypoint coordinates incorrect

Jeppesen NavData for cycle 2410, effective 3 October 2024, contains incorrect coordinates for the Enroute Waypoint NORUN. The correct coordinates for NORUN should be **N50 14.4 W096 18.5**. As a result, NORUN will be displayed incorrectly in Jeppesen Enroute Data Driven Applications.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2411, effective 31 October 2024. Until then an entry will appear in the EFB Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Electronic Chart Alert, please contact Chart Support at:

Support Portal: support.jeppesen.com

E-mail: ChartSupport@boeing.com

Electronic Chart Alerts are published to advise users of significant issues with charts displayed in electronic applications which may affect aircraft operations. Electronic Chart Alerts are distributed to electronic chart Users and are also available on Jeppesen's Web site.