



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 29 October 2024

Subject: Bogota, Colombia
El Dorado Intl (SKBO)
RNP Z Rwy 32L (AR) (12-20)
RNP Y Rwy 32L (AR) (12-21)

Missed Approach Climb Gradient missing.

Jeppesen charts RNP Z Rwy 32L (AR) (12-20) and RNP Y Rwy 32L (AR) (12-21) dated 23 DEC 22 (effective 29 Dec) does not depict the missed approach climb gradient. The procedures require a Missed Approach Climb Gradient of minimum 3.7%.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected RNP Z Rwy 32L (AR) (12-20) and RNP Y Rwy 32L (AR) (12-21) charts for will be reissued in the 22 NOV 24 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: support.jeppesen.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.