



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 3 January 2025

Subject: Windhoek, Namibia
Hosea Kutako Intl (FYWH)
RNAV Departures Rwy 08 (10-3), RNAV Departures Rwy 26 (10-3A)

Incorrect procedure titles.

Jeppesen charts, RNAV Departures Rwy 08 (10-3) and RNAV Departures Rwy 26 (10-3A), dated 22 NOV 24, Eff 28 Nov, have the incorrect procedure titles. **The correct procedure title for RNAV Departures Rwy 08 (10-3) should be UVORI 1A [UVOR1A]. The correct procedure title for RNAV Departures Rwy 26 (10-3A) should be UVORI 1B [UVOR1B].**

Please note: Procedure titles EGMAS 1A [EGMA1A] for Rwy 08 and EGMAS 1B [EGMA1B] for Rwy 26 remain **unchanged**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected charts for RNAV Departures Rwy 08 (10-3) and RNAV Departures Rwy 26 (10-3A) will be published in the next available revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: support.jepesen.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.