

!! URGENT!!

Date: 21 February 2025

Subject: Bhairahawa, Nepal

Gautam Buddha Intl (VNBW) RNP Rwy 28 (AR) (12-20)

Procedure information outdated

Jeppesen chart RNP Rwy 28 (AR) (12-20, dated 24 JAN 25) contains incorrect information for Gautam Buddha Intl; Bhairahawa, Nepal (VNBW).

RNP Rwy 28 (AR) should read RNP Z Rwy 28 (AR).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected chart will be reissued in the 7 MAR 25 revision. This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: <u>support.jeppesen.com</u> **E-mail:** ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.