



JEPPESEN[®]

Chart Alert

!! URGENT !!

Date: 25 November 2022

Subject: Male, Maldives
Velana Intl (VRMM)
Multiple procedures

Procedure information incorrect

Jeppesen charts dated 30 SEP 22 (effective 06 October 2022) contain incorrect information for Velana Intl; Male, Maldives (VRMM). AMDT 001-22 - dated 17 NOV 22 was received after the ICAO specified date for aeronautical information publication.

- [10-2E] STAR AQAXA 1B [AQAX1B]: Altitude at waypoints **MM522** and **MM425** should read “at or above” 5500'
- [10-2E] STAR TENIV 1B [TENI1B]: Altitude at waypoints **MM522** and **MM425** should read “at or above” 5500'
- [10-2C] STAR HOKEY 1B [HOKE1B]: Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “at or above” 5500'
- [10-2C] STAR ATSON 1B [ATSO1B]: Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “at or above” 5500'
- [10-2A] STAR PATLO 1B [PATL1B]: Altitude at waypoints **TUMSI**, **MM522** and **MM425** should read “at or above” 5500'
- [10-2J] STAR ELBET 1B [ELBE1B]: Altitude at waypoint **MM424** should read “at or above” 5500'
- [10-2G] STAR ESKOL 1B [ESKO1B]: Altitude at waypoint **MM424** should read “at or above” 5500'
- [10-2G] STAR MISAQ 1B [MISA1B]: Altitude at waypoint **MM424** should read “at or above” 5500'
- [10-2G] STAR DALSO 1B [DAL1B]: Altitude at waypoint **MM424** should read “at or above” 5500'
- [10-2D] STAR AQAXA 1A [AQAX1A]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.

- [10-2D] STAR TENIV 1A [TENI1A]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'
- [10-2A] STAR HOKEY 1A [HOKE1A]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'
- [10-2B] STAR ATSON 1A [ATSO1A]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'
- [10-2] STAR PATLO 1A [PATL1A]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'
- [10-2] STAR MUNUT 1C [MUNU1C]: Altitude at waypoints **MM503** and **MM502** should read “at or above” 5500'
- [10-2H] STAR ELBET 1A [ELBE1A]: Altitude at waypoint **MM505** should read “at or above” 5500'
- [10-2F] STAR ESKOL 1A [ESKO1A]: Altitude at waypoints **RONJI** and **MM505** should read “at or above” 5500'
- [10-2F] STAR MISAQ 1A [MISA1A]: Altitude at waypoints **RONJI** and **MM505** should read “at or above” 5500'
- [10-2F] STAR DALSO 1A [DALSO1A]: Altitude at waypoint **MM501** should read “at or above” 5500'
- [10-2] STAR MUNUT 1A [MUNU1A]: Altitude at waypoint **MM505** should read “at or above” 5500'
- [10-2H] STAR NASIM 1A [NASI1A]: Altitude at waypoint **MM505** should read “at or above” 5500'

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected charts will be reissued in the 9 DEC 22 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

For the coded NavData approach procedures, refer to the NavData Alert posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.