



JEPPESEN[®]

Chart Alert

!! URGENT !!

Date: 1 Dec 2022
Subject: Hyderabad, India
Rajiv Gandhi Intl (VOHS)

RNP Y Rwy 27R – missing procedure chart

Based on India AIP AIRAC AMDT 10/22 (eff 1 DEC 22) a new RNP Y procedure for RWY 27R is published at VOHS.

The chart will be included in revision 9 DEC 22 and is attached to the alert.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.