



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 15 May 2024

Subject: Mont-De-Marsan, France
Mont-De-Marsan (LFBM)

Procedure renamed, VOR and Transitions withdrawn

Procedure information outdated

The Jeppesen chart library contains outdated procedure information for Mont-De-Marsan (LFBM), France. The changes from FRANCE MIL AMDT 06/24 could not be incorporated in time for the effective date **16 MAY 24** and the following procedures are affected:

SID RWY 09	Deletion of SAU VOR
SID RWY 27	Deletion of SAU VOR
Initial Approach RWY 09 via CORMA	Renamed from procedure Z, deletion of SAU VOR.
Final Approach PAR RWY 09	Renamed from procedure Z.
RNP RWY 09	Renamed from procedure Z.
Initial Approach RWY 27 via CORMA	Renamed from procedure Z, deletion of SAU VOR.
Final Approach ILS or LOC RWY 27 (Military)	Renamed from procedure Z.
Final Approach PAR RWY 27	Renamed from procedure Z.
RNP RWY 27 (LPV only)	Renamed from procedure Z.

The updated procedures will be published with revision 31 MAY 24.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.