

## **!! URGENT !!**

Date: 13 May 2024

Subject: Ankara, Turkiye Etimesgut (LTAD)

> TACAN A (24-1) TACAN B (24-2) TACAN C (24-3)

## Procedure information not included

Jeppesen chart library does not contain information for Etimesgut; Ankara, Turkiye (LTAD). Turkiye AIP AIRAC AMDT 004/2024 (effective 16 MAY 24) contains newly added instrument approach procedures. The new procedure charts could not be published in time and are therefore not included in revision 10 MAY 24, for the 16 MAY 24 effective date.

Below charts and procedures are missing from library:

- TACAN A (24-1)
- TACAN B (24-2)
- TACAN C (24-3)

The procedure charts will be published in revision 24 MAY 24 and added to this Chart Alert when available. The published charts (dated 24 MAY 24) will be effective 16 May 2024. The charts will also be available for download from <u>www.jeppesen.com</u>

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

If you have any questions concerning this Chart Alert, please contact Chart Support at: +1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere) U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at <u>www.jeppesen.com</u>.