

!! URGENT!!

Date: 25 June 2024

Subject: Luang Phabang, Laos

Luang Phabang Intl (VLLB)

Multiple procedures

Procedure information outdated

Jeppesen charts dated 10 MAY 24 (effective 16 May 2024) and 7 JUN 24 contain outdated information for Luang Phabang Intl; Luang Phabang, Laos (VLLB). Laos SUP A01/24 has been cancelled.

Below procedures should not be used:

- 10-2B RNP ARRIVALS ATVAM 1C, BEGOM 2C, IBASI 1D, IDVAT 1C, KAASI 1E, OBDET 1C, OSVER 1C, SAMDI 1C, UPLIX 1C, VEDVU 1C
- 10-2C RNP ARRIVALS ATVAM 1D, BEGOM 2D, IBASI 1E, IDVAT 1D, IDVAT 1E, KAASI 1F, OBDET 1D, OSVER 1D, SAMDI 1D, UPLIX 1D, VEDVU 1D
- 10-3B RNP DEPARTURES ATVAM 1B, IDVAT 1B, OSVER 1B, SAMDI 1B, UPLIX 1B, VEDVU 1B
- 10-3C RNP DEPARTURES ATVAM 1A, OSVER 1A, UPLIX 1A, VEDVU 1A
- 10-3D RNP DEPARTURES BEGOM 2A, IBASI 1B, IDVAT 1A, KAASI 1C, OBDET 1A, SAMDI 1A
- 10-3E RNP DEPARTURES BEGOM 2B, IBASI 1C, KAASI 1D, NIXOG 1A, OBDET 1B

Below charts are missing from library and are attached to this alert:

- 10-2B RNAV (GNSS) ARRIVALS LAPON 1C, NAMON 1E
- 10-2C RNAV (GNSS) ARRIVAL NAMON 1F
- 10-3B RNAV (GNSS) DEPARTURE NAMON 1C
- 10-3C RNAV (GNSS) DEPARTURE NAMON 1D

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected charts will be reissued in the 5 JUL 24 revision. This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107 E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.