



JEPPESEN[®]

Chart Alert

!! URGENT !!

Date: 3 July 2024

Subject: Washington, DC (VA)
Washington Dulles Intl (KIAD)
RNAV (RNP) Z Rwy 19L (22-23)

Missed Approach Icon Turn Direction Incorrect

The Jeppesen RNAV (RNP) Z Rwy 19L (22-23) chart dated 10 MAY 24 (effective 16 May 2024) has a missed approach icon turn direction depicted incorrectly.

The missed approach icon should depict **climbing LEFT turn to 3000'**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected RNAV (RNP) Z Rwy 19L (22-23) chart will be reissued in the next available revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.