

## !! URGENT!!

Date: 9 July 2024

Subject: Nakatsu, Japan

Tsuiki (RJFZ)

Tacan Rwy 07 (14-1)

Waypoints names incorrect

Jeppesen chart Tacan Rwy 07 (14-1) dated 10 MAY 24, effective 15 May 2024, 1500Z contains incorrect information for Nakatsu; Tsuiki, Japan (RJFZ). Changes in Japan AIP AMDT 008-24 dated 11 JUL 24 could not be published in time.

Changes for **Tacan Rwy 07 (14-1)**: waypoint UPGUN should read ENLUG, waypoint VABLA should read IPDIM.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected chart for Tacan Rwy 07 (14-1) will be reissued in the 19 JUL 24 revision. This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere) U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at <a href="https://www.jeppesen.com">www.jeppesen.com</a>.