

## !! URGENT !!

Date: 26 July 2024

Subject: Hong Kong, PR of China

Hong Kong INTL (VHHH)

Construction work and Flight Check of RWY 07C/25C

The AIP SUP 05/24 (dated 22 JUL 24) provided updated information for Hong Kong, Hong Kong INTL (VHHH) airport about "Works Progress and Flight Check of Centre RWY 07C/25C Under Reconfiguration".

This information will be depicted on new 10-8B temporary chart (dated 2 AUG 24). This alert is published for situational awareness, because some work will already start at 31 JUL 24 while flight checks will be conducted between 4 AUG 24 and 11 SEP 24:

- The security fence separating the closed RWY 07C/25C and associated taxiways from the operational area will be replaced by marker boards. Pilots may have a clearer view of the non-operational areas still under construction.

Nevertheless, the enclosed area remains non-operational and the RWY 07C/25C and associated taxiways are still not open for aircraft operations.

Pilots shall closely follow ATC instructions and are reminded to be vigilant when crossing the RWY 07C/25C.

The chart will be published with revision 2 AUG 24.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

This Chart Alert is also posted on the Jeppesen Web site: Notices and Alerts.

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere) +49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107 E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at <a href="https://www.jeppesen.com">www.jeppesen.com</a>.