



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 20 November 2024

Subject: Caslav, Czechia
Caslav (LKCV)
ILS DME Rwy 31 (11-1),
(GPS) NDB Rwy 13 (16-1) (CAT A & B),
(GPS) NDB Rwy 13 (16-2) (CAT C & D),
(GPS) NDB Rwy 13 (16-3) (CAT C & D, MILITARY ONLY),
NDB Rwy 31 (16-4)

Radials and bearing not updated.

Jeppesen charts ILS DME Rwy 31 (11-1), (GPS) NDB Rwy 13 (16-1), (GPS) NDB Rwy 13 (16-2), (GPS) NDB Rwy 13 (16-3), and NDB Rwy 31 (16-4) dated 5 APR 24, Eff 18 Apr have outdated radial and bearing values. The corrected values should be as follows:

ILS DME Rwy 31 (11-1): R-090 VLM at SUKAV
(GPS) NDB Rwy 13 (16-1): R-011 VLM at ERUSO, R-091 OKL at GOLIN, R-066 VLM at EKNEV
(GPS) NDB Rwy 13 (16-2): 074 degrees from GOLIN to D12.8 CF, R-011 VLM at ERUSO, R-091 OKL at GOLIN, R-066 VLM at EKNEV
(GPS) NDB Rwy 13 (16-3): R-011 VLM at ERUSO, R-091 OKL at GOLIN, R-066 VLM at EKNEV
NDB Rwy 31 (16-4): R-090 VLM at SUKAV, R-088 VLM at PIMEK

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected ILS DME Rwy 31 (11-1), (GPS) NDB Rwy 13 (16-1), (GPS) NDB Rwy 13 (16-2), (GPS) NDB Rwy 13 (16-3), NDB Rwy 31 (16-4) charts will be reissued in the 6 DEC 24 revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: support.jeppesen.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.