



!! URGENT !!

Date: 21 February 2025

Subject: Bhairahawa, Nepal
Gautam Buddha Intl (VNBW)
RNP Rwy 28 (AR)
Cycle 2502

Procedure information outdated

Jeppesen NavData for cycle 2502, effective 20 February 2025, contain incorrect data for Gautam Buddha Intl; Bhairahawa, Nepal (VNBW).

RNP Rwy 28 (AR) should read RNP Z Rwy 28 (AR).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2503, effective 20 March 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.