



JEPPESEN®

Chart Alert

!! URGENT !!

! Update !

Date: 04 June 2024

Subject: Paluknys, Lithuania
Paluknys (EYVP)
VFR Approach Chart 19-1

Incorrect Approach Frequency

The Jeppesen VFR Approach chart 19-1 for Paluknys, Lithuania (EYVP), dated 24 MAY 24, depicts an incorrect approach frequency.

The only frequency for Vilnius Approach is **120.705**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

The corrected chart will be reissued in the 21 JUN 24 revision and is attached. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at www.jeppesen.com.