



JEPPESEN®

Chart Alert

!! URGENT !!

Date: 27 December 2024


Subject: Jeju, Korea
Jeongseok (RKPD)
VOR Rwy 01 (23-1)

Circle-to-land minimums incorrect

Jeppesen chart **VOR RWY 01 (23-1)** dated 22 NOV 24 (effective 27 November 2024, 1600Z) contains incorrect information for Jeju, Korea; Jeongseok Airport (RKPD).

Circle-to-land minimums should include a number 2 square flag:

Std	STRAIGHT-IN LANDING CDFA		CIRCLE-TO-LAND	
	DA/MDA(H) 1820' (718')		Not Authorized West of Rwy 01-19	
	ALS out		Max Kts	MDA(H)
A			100	1920' (746') 2 V1500m
B	R2900m	R3300m	135	1920' (746') 2 V1600m
C			180	2020' (846') 2 V2400m
D			205	2020' (846') V3600m



NO CIRCLING

1 VNAV DA(H) in lieu of MDA(H) depends on operator policy. **2** or higher straight-in minimum.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!

The corrected chart for will be reissued in the next available revision. This Chart Alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

Support Portal: support.jepesen.com

E-mail: ChartSupport@boeing.com

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site.